			J	
l. Municol	Hita	Setain Text	Dr	Time stamp
3	4.3	981/102 and Strelay same circuit near	USPAT	2003/07/01 10:51
		DIPARTY	**, * * *, ***	2003/07/01 10:51
•••	2.71	161,101 and Strelay same corouit mean	USPAT	2003/0./01 10:51
		preaker and current near limit\$3	יווי הייי	2003/07/01 10:51
6	19	361/104 and Strelay same fuse and	USPAT	2003/01/01 10:01
		current near limit\$3	USPAT	2003/07/01 10:52
**	20	361/93.9 and \$5relay same current near	USPAI	2003/07/01 10:52
		limit\$3	HUDAT	2003/07/01 10:55
:		661/93.1 and Shrelay same fuse	USPAT	
5	દન	361/104 and \$5relay same fuse	USPAT	2003/07/01 10:58
-	1	"19850397"	EPO;	2003/05/17 19:27
			DERWENT	0001/06/06 10 17
-	5	"2212679"	EPO;	2005/06/26 13:47
			DERWENT	000-106/06 16 46
-	19		USPAT	2003/06/26 12:48
-	9		USPAT	2003/07/01 10:42
-	1	"5374792",PN.	USPAT	2003/06/26 13:05
•	1	"5430597".PN.	USPAT	2003/06/26 13:05
	1	"5454904".EN.	USPAT	2003/06/26 13:05
-	-	"6317530".PN.	USPAT	2003/06/26 13:05
-	1	"6373007".PN.	USPAT	2003/06/26 13:06
	-	"6317530".PN.	USPAT	2003/06/26 13:06
-	502	361/93.1	USPAT	2003/06/26 15:10
-	312	361/93.9	USPAT	2003/06/26 13:10
-	517	361/99	USPAT	2003/06/26 13:10
-	340	200/181	USPAT	2003/06/26 13:10
-	17ē	200/10	USPAT	2003/06/26 13:11
-	240	200/270	USPAT	2003/06/26 13:11
	1455	300/275	USPAT	2003/06/26 13:11
	151	218/2	USPAT	2003/06/26 13:11
	146	218/7	USPAT	2003/06/26 13:11
-	130	218/30	USPAT	2003/06/26 13:11
-	96	218/16	USPAT	2003/06/26 13:11
•	182	218/48	USPAT	2003/06/26 13:12
	235	018/146	USPAT	2003/06/26 13:12
	2088	307/112	USPAT	2003/06/26 13:12